


# 3 Axis Cross Vises



# 3 Axis Cross Vises

## Description

- Cross clamp is used in two mutually perpendicular feeding mechanisms, it can be moved in the direction of X and Y at the same time, and it can be rotated 360° with a swivel base.
- When it is compatible with a bench-type drilling machine, it can drill several holes and mill several slots. on the same face once time by the way of hand-operated feeding in two mutually perpendicular directions It can be used as an attachment for milling machine and grinding machine or as a tool used only.

## SPECIFICATIONS

| model | width of jaw(mm) | height of jaw(mm) | max. opening(mm) | G. weight/N. weight(kg) |
|-------|------------------|-------------------|------------------|-------------------------|
| 200   | 200              | 53                | 203              | 37/35                   |
| 150   | 160              | 53                | 152              | 28/27                   |
| 125   | 125              | 50                | 125              | 19/18                   |
| 100   | 75               | 35                | 76               | 8/9                     |

