

# 3 Axis Cross Vises




Image not found or type unknown



# 3 Axis Cross Vises

## Description

- Cross clamp is used in two mutually perpendicular feeding mechanisms, it can be moved in the direction of X and Y at the same time, and it can be rotated 360° with a swivel base.
- When it is compatible with a bench-type drilling machine, it can drill several holes and mill several slots. on the same face once time by the way of hand-operated feeding in two mutually perpendicular directions It can be used as an attachment for milling machine and grinding machine or as a tool used only.

## SPECIFICATIONS

model	width of jaw(mm)	height of jaw(mm)	max. opening(mm)	G. weight/N. weight(kg)
200	200	53	203	37/35
150	160	53	152	28/27
125	125	50	125	19/18
100	75	35	76	8/9

